

Important

FOLDING OF EDX 9000-T

- only in event of connection of all hydraulic supply lines
- only in event of connection of AMATRON+.

To avoid damaging the machine, fold the machine extension arms as described in the operating manual, section "Folding machine extension arms in/out".

Machine damage that can occur due to incorrect folding

The seed hoppers may be damaged during folding out, resulting in machine failure, if the supports (1) are not on the upper plastic rails (2) before folding out.



During folding, the lighting can be damaged if the free hydraulic return flow is not connected to the tractor.



en

MG4347
BAH0032.0 03.09